Filing Date: June 30, 2003 Title: RATE MATCHING APPARATUS, SYSTEMS, AND METHODS

IN THE DRAWINGS

The Examiner objected to the drawings, asserting that Figures 1-3 and 5 appeared to have faded bus lines and faded elements and thus were hard to see.

Corrected drawings are supplied herewith, each labeled as "REPLACEMENT SHEET". Figures 1-7 have each been corrected by clarifying the bus lines and elements. No new matter is introduced.